


# PLE LIGHTING

3488

## INSTALLATION INSTRUCTIONS:



- 1, Ensure mains supply is switch off.
- 2, Fit back plate with crossing bar(1) onto mounting surface with self-tapping screws (2).
- 3, Make the wiring connections: Using wire connectors (3) connect the house white wire(s) to the fixture white( or ribbed) lead(s); connect the house black( or red) wire(s) to the fixture black( or smooth) lead(s). Make sure there are no exposed wires or stands, and the connections are secured.
- 4, Fit ceiling canopy (4) onto back plate with screws (5).
- 5, Fit crystal shade( 6) onto lampholder (7), screw in the socket ring (8) onto socket with socket driver(9).
- 6, Fit bulb( 10) firmly into lampholder..

### WARNING :

- Electricity supply required 110-120v 60 htz alternating current.
- Use only the correct light bulbs as stipulated on the luminaries .
- Disconnect the power and allow fitting cool down before cleaning or changing bulb(s).
- If any malfunction occurs, switch of mains and contact a qualified electrician .
- Do not modify this unit in any manner.